

RFCA ESTABLISHED MILESTONES FY99

M1	Either a) ship cumulative amount of 78% of 10/01/96 pond/salt inventory offsite and evacuate all waste from Tent 9 by 9/30/99, or b) the additional onsite storage for pond/salt is operational by 9/30/99.
M2	Ship 670 m ³ of TRU/TRM to WIPP by 9/30/99, assuming a January 1999 opening.
M3	Ship 1,750 cubic meters of low level waste by 9/30/99.
M4	Complete installation and operate remedial action described in decision document for Solar Pond plume (N. Walnut Creek) by 9/30/99.
M5	Complete installation and operate remedial action described in decision document for East Trenches/903 Pad/Ryan=s Pit Mound plume (S. Walnut Creek) by 9/30/99.
M7	Develop a comprehensive characterization/remediation strategy for the Industrial Area soils and ground water by 9/30/99.
M8	Complete off-site shipment by 9/30/99 for treatment and/or disposal of all T-1 waste streams not returned to T-1, and for which treatment or disposal locations are available and controlling documents are in place by 4/30/99.
M9	Complete information management system for integrated sitewide monitoring and environmental database by 9/30/99.
M10	Either a) construct and operate new facility for storage of TRU/TRM by 9/30/99, or b) by 9/30/99 demonstrate adequate storage available for TRU/TRM through 9/30/00.
M11	Complete characterization of the 903 Pad as defined in the approved Sampling Analysis Plan by 9/30/99 (with the exception of the remaining radiologic boreholes, which will be completed by 12/31/99).

RFCA ESTABLISHED TARGET ACTIVITIES FY99

T1	Thermally stabilize 90% of the plutonium oxide generated during the year by 9/30/99.
T2	Complete the offsite shipment of the pits by 9/30/99.
T3	Drain 6 systems in building 771 by 9/30/99.
T5	Remove solid Cat I and II SNM (not holdup or composites) from building 776/777 by 9/30/99.